

Guarantee for Prefabricated Domestic Swimming Pool Liners 0.75mm (30 thou)

5 Year Limited Guarantee

Should any material fault or manufacturing defect covered by this guarantee become apparent within 12 months of purchase, the pool liner will be repaired or replaced free of charge.

If such a fault occurs at any time during the following 4 years then the value of the guarantee shall be pro rata from the date of purchase – i.e. the purchaser will be required to pay the full list price of the liner at the date of the claim less 1.60th of that price for each full month remaining in the guarantee period. This guarantee is non-transferable and is applicable to the original purchaser only.

Conditions

This Guarantee covers: -

 Defects in the liner materials and faulty workmanship where the liner has been installed correctly by competent persons in a suitable pool structure and operated under normal domestic conditions

This Guarantee does not cover: -

- Pool liners that have been subjected to alteration, misuse, abuse, neglect, accident or flood.
- Damage caused through incorrect chemical balance. Chemical levels must be kept within the levels recommended by their manufacturers. Very high levels of water sanitizers will cause the liner to fade and creasing of the lining materials may occur.
- Pool liners that operate at water temperatures in excess of 33°C (91°F).
- Pool liners that have been drained of water other than by a competent pool fitter.
- Liners installed on sites with a high-water table or underground springs without a professionally installed dewatering system.
- Pool liners installed on rough or incompatible pool shell surfaces.
- Misalignment of liner patterns. The flexible characteristics of the liner material makes it impossible to align the pattern on the material during manufacture.

Exclusions

- No liability for consequential costs or incidental damage arising from a defective pool liner will be accepted.
- No liability will be accepted for any damage to property or injury to persons or animals caused directly or indirectly by the pool liner.