

Dear Fastlane Owner,

We hope that you are enjoying your Fastlane by Endless Pools. We have been receiving terrific feedback from our customers who are using it for swimming, training, and more family fun than we ever imagined.

We have also learned that salt-chlorine generators are more harmful than first thought. Endless Pools, like other equipment manufacturers, made specific provisions for these systems in our warranty. Salt chlorine generators create inherent risk for all pool equipment, particularly lights, ladders, heater components, and pump seals.

Placing a Fastlane in a pool which is sanitized using a salt-chlorine generator creates increased risk of a hydraulic system failure and oil leaks.

Any Fastlane placed in this type of environment must be properly bonded, and water chemistry must be closely monitored. As stated in our warranty, pH levels must be maintained between 7.4 and 7.8, total alkalinity between 80 and 120 ppm, salt chlorine levels of 4000 ppm, and total dissolved solids below 7000 ppm. Failure to properly bond the Fastlane or maintain proper water chemistry will void the warranty.

IF YOU ARE USING A SALT-CHLORINE GENERATOR, PLEASE COMPLETE THE FOLLOWING TASKS:

1. Remove and inspect your Fastlane unit annually. Once removed, rinse the Fastlane with fresh water before storing for the off-season.
2. Replace the underwater hydraulic motor and submersible hoses every two years.
3. Ensure that the fluid level in your power unit is no more than one cup above the float level switch (see supplementary instructions). This simple procedure ensures that any oil leak is minimized.

These measures will help avoid problems and protect your pool.

Please feel free to call our Customer Service Department at 800-910-2714 with any questions.

Regards,

Endless Pools Customer Service